



File path: S:\13800\13838\13838.002\Figures\20120210_SIT\AI\Figure_02.ai; Date: 07/27/2012; User: Jereme Chandler, LCI

Explanation

- Hosgri Fault Zone, slip rate >1mm/yr
- Fault with estimated slip rate <1mm/yr
- Los Osos Structural Block
- San Luis/Pismo Structural Block
- Santa Maria Valley Structural Block
- 2D Survey area extent
- 3D Survey area extent

Notes: 1. Locations of faults shown on map are from PG&E (2011b).
 2. Basemap is 2010 PG&E Project DEM.

<p>Structural blocks and faults in the DCPP area</p>	
<p>DCPP 3D/2D Seismic-Reflection Investigation</p>	
Pacific Gas and Electric Company	Figure 2