94CCT02 8/9/94 - 8/19/94

8/9/94 South Carolina MS. Coastal



- boat 8Kw running computer etc
- U.S.G.S. 4.5 KW Gen, 220V running P.S. (Hunter)

Hunter
Geolink XDS 3
Delph 2
No Depth

- ups used on computer

File names SC/mo/day/_line#.DAT - seismic
SCNAV_line # - nav lines

SC NAV_1.DAT - nav lines
SC89_1.DAT scis. lines

Recording fix 102 - seismic
fix 104 - nav.

SOL SC89_1 15:11 Fix1 - Wappo Chan. (Intercoastal
SOL SCNAV_1 15:11 Fix1

EOL SC89_1 15:18
SCNAV_1 15:18

8/10/94

SOL - SCNAV_2.DAT - NAV 09:22

SOL SC810_2.DAT - Seismic 09:30 fix 12 175 Joules

EOL SC810_2 fix 29 09:50

SOL SC810_3 fix 35 10:02 75 Joules

EOL SC810_3 fix 49

SOL SC810_4 10:04 fix 50
fix 61 - rearranging sled/phase config
fix 64 turn
fix 67. config moved 3m back
paused/restart fix 74 - power increase 175 Joules 10:27
fix 108 Gps pwr off - No nav
fix 109 Gps on (DGPS on) 10:58
fix 199 NOTE AT SHOT 32700, number of shots receives and next shot is -37000 and goes up (-36000, -35000 ...etc)

EOL SC810_4 fix 218 12:36

SOL SC810_5 fix 219 12:37

EOL SC810_5 fix 298 13:53

SOL SC810_6 fix 299 13:53 turn east
fix 317 14:12 inshore turn

EOL SC810_6 fix 364 10:57

SOL SC810_7 fix 366 10:58 turn North

EOL SC810_7 fix 496(?) 15:55

EOL SCNAV_2 15:55

8/11/94 S. Carl

SOL SCNAV_3 08:07

SOL SC811_8 fix 15 08:22 → -change MC length to 80m
choppy 3' seas

fix 46 – fix 55 individual hydrophone test

EOL SC811_8 fix 63 09:10

SOL SC811_9 fix 64 09:12

EOL SC811_9 fix 108 09:51

SOL SC811_10 fix 125 10:03

EOL SC811_10 10:49

SOL SC811_11 11:51

EOL SC811_11 fix 237 13:11

SOL SC811_12 fix 332 13:16

EOL SC811_12 fix 344 13:28

SOL SC811_13 13:31 fix 346

14:23 fix 403 paused to position sled further back

14:26 fix 408 restart

14:27 fix 409 pause to readjust

14:31 fix 412 restart (plate 12m, mid hydrophone)

EOL SC811_13 14:33 fix 415

SOL SC811_14 14:34

EOL SC811_14 14:58 fix 445

SOL SC811_15 14:59 fix 447

EOL SC811_15 15:00 fix 517 power upto 375

SOL SC811_16 16:04 fix 520

EOL SC811_16 fix 550 16:33

EOL SCNAV_3

8/12/24 choppy

SOL SCNAV_4 0:842

SC812-17 fix 17 08:57
fix 49 fish & phones set back to 4m

EOL SC812-17 fix 161 11:04

SOL SC812-18 fix 161 11:10
EOL SC812-18 fix 216 15:59

SOL SC812-19 12:04 fix 220

EOL SC812-19 12:54 fix 270

EOL SC NAV_4 12:55

8/14/94 — 2nd 30uF, 6000V cap installed
- NOT connected up -
- 60 joules

SCNAV_5 Nav fil 09:23

SC814_20 Seismic SOL fix 9 09:31 - float on end of phase
fix 10 paused - float moved to seperate line
beat circle
fix 20 restart line, p.s. off
fix 21 ps on still circling
fix 26 on line
fix 65 pause power up to 135
fix 66 start
fix 74 paused power to 75
fix 75 recording
fix 132 paused power to 135
restart

EOL SC814_20 fix 190 12:10

SOL SC814_21 fix 192 12:12

EOL SC814_21 fix 229 12:45

SOL SC814_22 fix 269 13:18

EOL SC814_22 fix 379 14:44

SOL SC814_23	fix 436	15:41	Steamboat Chan
EOL SC814_23	fix 490	16:28	
EOL SCNAV_5	16:29		

8/15/94

SOL SCNAV_6 new

SOL SC815_24 seis 11:17 fix 3 60 joules
between fix 15/fix 16 - power up to 135 joules
fix 33/34 - power down to 60

EOL SC815_24 fix 245 15:01

SOL SC815_25 fix 301 15:54

EOL SC815_25 fix 365 16:48

EOL SCNAV_6

8/16/84

SOL SCNAV_7 09:31 now avg 80sec

SOL SC816_26 09:36 fix 10 -
fix 29 - now avg min
fix 37 - power up to 69 Joules
fix 68 - power to 135

EOL SC816_26 13:09 fix 248

SOL SC816_27 13:36 fix 268

EOL SC816_27 14:44 fix 335
EOL SCNAV_7

8/17/94

SOL SCNAV_8 8:22

SOL SC 817_28 8:44 EOL 906.
SOL SC 817_29 910 EOL 912
SOL SC817_30 11:29 Fix 320 EOL 1216 Fix 466
SOL SC817_31 12:54 Fix 543 EOL 1503 Fix 604

8/18/91

SOL SCNAV_9

SOL SC818_32 09:08 Fix 8
Fix 52 pur changed to 135
EOL SC818_32 fix 107 10:48

SOL SC818_33 Fix 312 14:15

EOL SC818_33 Fix 350 14:53

8/19/94

SOL SCNAV_10 08:22

SOL SC819_34 08:22 fix 1 power @ 025

fix 8 power down to 60

fix 9 power to 135