90-1988

D WOODROW

re ID SFR 022190/3N/H90-1988 | Depth | Date Processed 062995
n SOUTH SF BAY | Core Length | Photo X-RAY 060606
eet 1 of 1

General Description

X-RADIOGRAPH DETAILS ON 90-198A LOG.

Color Biotin



UNIT #1 CLAY, V. LITTLE SILT, SOFT, BLOTCHY
0-12cm N3/1-5Y 3/2, H2S FIZZ/ODOR
LAMINAE ACC COLOR-BANDS mm-
CM. NO SHELL. BOTTOM CONTACT
UNKNOWN.

BURROWS
0-25

BURROW

FRACTURES

NO DETAILS VISIBLE

DISCONTINUITIES