90-5B

SFB01239/5/G/23 90-5B REENTERED INTO DB 022210

re ID ~~SFB01239/5/G/23 90-5A~~

PROCESSED: 070505

X-RADIOGRAPH ANALYSIS: 063005

2 of 2

Color Biotin



END OF 90-5A 72cm

UNIT #4 CLAY, SILTY, SOFT, 2.5Y 4/2, NO SHELLS, VAGUE LAMINAE NO ACID/$H_2S$ FIZZ

~~69-85cm~~ 81-97

97 ~~85cm~~ ~~85cm~~ EROSION SURFACE (X-RAY)

151.5

SHELL ~~190cm~~ EROSION SURFACE 102 CUT AND FILL

SHELL

FRACTURE

SHELLS

UNIT #5 CLAY, SILTY, SOFT, 10Y 3/1 (UNOXIDIZED) 2.5Y 4/2 DK GRYSH BRN, SCATTERED SMALL SHELLS NO ACID/$H_2S$ FIZZ, THICK, VAGUE LAMINAE, BOTTOM CONTACT UNKNOWN

~~85-151.5~~ 97-163.5

SHELLS

10Y 3/1 DK GRYSH GRY

SHELLS

2.5Y 4/2 DK GRYSH BRN

163.5