91-52

ENTERED INTO DB 11 0909

NO X-RAY

Core ID 020791/2 91-52	Depth	Date Processed 12/4/03
Location SAN PABLO BAY	Core Length 1.29m	Photo
Sheet 1 of 2		

General Description

CLAY, W/SILT LAMINAE, BURROWED. DISRUPTED 40-61cm, SHELLS @121-124cm. MANY EROSION SURFACES.



GAP

10YR 3/2 V dk grysh brn

BURROW

SILTY CLAY

GAP

SILTY CLAY

BURROWS

UNIT 1 CLAY, 10YR3/2, SILTY IN LAMINAE 0-129.5cm BURROWED. DISRUPTED IN PART, SHELLS 120.5-123cm.

GAP (EROSION SURFACE, 1/8/04)

DISRUPTED 38-108cm

10YR 3/2

GAP

DISRUPTED

GAP

GAP

GAP

Color	BiotIn

91-52

Core ID 020791/2 91-52

Sheet 2 of 2

			Color	BioIn
		GAP		
80				
		GAP		
90		FRACTURE/GAP		
		GAP		
100		SILTY CLAY		
		(EROSION SURFACE, 1/8/04)		
		10YR3/2		
		GAP		
110		SILTY CLAY		
		(EROSION SURFACE, 1/8/04)		
120		SILTY CLAY		
		SHELLY SILT (SAMPLED)		
		BROKEN		
130		END OF CORE SEGMENT 129cm		
140				
150				

UNIT 1