91-54

ENTERED INTO DB 120909 X-RADIOGRAPH

Core ID 020791/4 91-54	Depth	Date Processed 11/06/03
Location SAN PABLO BAY	Core Length 0.93m	Photo
Sheet 1 of 2		

General Description

SAND W/ CLAY, SAND IS F-M, BURROWS, FRAG SHELLS; INCLINED STRATA @ 70-80cm



EROSION SURFACE

UNIT 1: SAND W/ CLAY STRATA, SAND IS F-M, 0-93cm CLAY & SAND 10YR3/2, BURROWED. INCLINED STRATA @ 70-80cm

10YR3/2 V. dk. grysh brn.

EROSION SURFACE (2/19/04)

10YR3/2 SHELL, UPSIDE-DOWN FISHHOOK

F/MS

GAP

EROSION SURFACE

Color	BioIn

91-54

Core ID 020791/4 91-54

Sheet 2 of 2

Color | BioIn



STRATA WELL DEFINED (DISRUPTED?! 1/12/04)

SILTY MUD CLAST w/WOOD (C14)
EROSION SURFACE (2/19/04)

SANDY CLAY

80
90
100
110
120
130
140
150