CHANNEL COAST, WEST SIDE
5m BMLW
ENTERED INTO DB

10-142A

DWOODROW

ore ID SFB 021290/1 90-142A	Depth	Date Processed 091205	
on SOUTH SF BAY	Core Length 1.465 m	Photo X-RADIOGRAPH ANALYSIS 091205	
eet 1 of 2			

General Description

X-RADIOGRAPH DEPTHS ARE FROM TOP OF SEDIMENT, NOT TOP OF CORE LINER.



Depth	Description	Color	Biotin
0	SHELLS + SED CLASTS — 1.5cm PLASTIC PACKER AT TOP. UNIT #2 DEBRIS 0-6.5cm SURFICIAL.		
	6.5cm EROSION SURFACE — 10Y 3/1 DK GRNSH GRAY		
10	UNIT #2 CLAY, SILTY, 10Y 3/1 DK GREENISH GRY, 6.5-50cm W/ BURROWS, LAMINAE, FEW SHELL		
20	20cm EROSION SURFACE		
	SHELL		
	BURROWS, LONG		
30	10Y 3/1		
	GASTROPOD		
40	FRACTURE W/ GAP 39cm		
	UNIT #3 COQUINA + CLAY 10Y 3/1, COQ IS 50-146.5 cm (→F BOTTOM TO TOP IN SEVERAL SEQ W/ EROS SURF AT TOP. BURROWED TO 68cm. CLAY DS OF #1. 50-52cm IS SANDY COQ.		
50	50cm EROSION SURFACE		
	51cm FINE SHELL DEBRIS (COQUINA) WITH M/S MICA		
	53.5 EROSION SURFACE — BOTTOM CONTACT		
	COQUINA		
60	59cm 14 SAMPLE, 60-62cm (755 yrs BP, NOSAMS)		
	FEW BIG SHELLS, SANDY		
	64cm EROSION SURFACE		
	BURROWS, SHORT		
70			