NOTE- BADLY BROKEN DURING SPLITTING

ENTERED INTO DB 11/15/09 90-109a

NO X-RAY

Core ID SFB020790/10	Depth	Date Processed 11/18/03
Location SAN PABLO BAY	Core Length 1.32 m	Photo
Sheet 1 of 2		

General Description

CLAY, MOIST, DENSE, V. LITTLE SILT, NO SHELLS. OXIDIZED TO 2.5Y 3/2 FROM 10YR 4/2, FEW ORGANICS. SCATTERED STRATA OF VF-FS, MICA, MANY @ 37-43cm. EXTREME SOFT SED DEFORMATION 46-89 cm, HORIZ BELOW

Depth	Description	Color	BiotIn
0			
10			
20	BROKEN, MUCH RED-STAINING ON GAPS + FRACTURES		
	BARROWS		
30	2.5Y 3/2 V dk grysh brn (FRESH COLOR) EROS SURF (2/18/04)		
40	10YR 4/2 dk grysh brn (WEATHERED) EROS SURF (2/18/04)		
	EROSION SURFACE (2/14/04)		
	FS IN STRATA + LENSES (RIPPLE?)		
	GAP		
	ESURF (2/18/04)		
50			
60			
70			

UNIT 1

COMPLETELY DISRUPTED STRATA* 46-89cm

UNIT 1 CLAY, MOIST, DENSE, OXIDIZED 0-132.5cm 2.5Y → 10YR. LITTLE SILT, SAND VF-F IN SCATTERED STRATA, ESP @ 37-43cm. SOFT-SED. DEFORMATION @ 46-89cm. STRATA @ 89-114cm are INCLINED @ ~ ∡10° HORIZ BELOW. NO SHELLS. FEW ORGANICS

* MOSTLY ALL CLAY

90-109a

Core ID 020790/11

Sheet 2 of 2

		Color	BioIn
80			
90			
100			
110			
120			
130			
140			
150			



<10°

EROS LINE (2/18/04)

10YR 4/2 dk grysh brn

BROKEN GAP. W/IRON-STAINING

ALMOST HORIZONTAL STRATA

COLOR Δ

2.5Y 3/1 blk

END OF CORE 132.5cm