90-115B

DESCRIPTION COMPLETED LOGGED FROM A SPLIT MADE BY OTHERS.

Core ID 020790/16B 90-115B	Depth	Date Processed 12/1/03 - 12/16/03
Location SAN PABLO BAY	Core Length 1.295 m	Photo
Sheet 1 of 2		

General Description

CLAY, SOFT, MOIST, 2.5Y 3/1 - 5Y - 10Y V dk gry, blk, greenish-gry w/ SILT/VFS LAMINAE OR EROSION SURFACES. FEW ORGANICS, SHELLS @ 36-41, 208-214, 245-248. DISRUPTED @ SEVERAL HORIZONS. BURROWS

Color BioTrb

BASE OF UNIT 4. ES 138cm

2.5Y 3/1 V dk gry

UNIT 5 CLAY, VARIOUS SHADES OF GRY 139-254 cm W/ THIN SILTY SAND STRATA, VERT. BURROWS (IRON-STAINED) IN UPPER 35cm, RARE BELOW, SHELL RARE, ORGANICS RARE NOT DISRUPTED ?

DISRUPTED 18-31cm

VERTICAL BURROWS OR IRON-STAINED FRACTURES

EROSION SURFACES W/ SAND LAMINAE OR EACH 139-160cm

SHELL

DISRUPTED 34-59cm

ORGANICS

5GY 3/1 dk grnish gry

ORGANICS

ES 184-185cm

GAP ABOVE SAND

ORGANICS

DISRUPTED 63-74cm

10Y 2.5/1 greenish blk.

90-115B

Core ID 020790/16B 90-115B

Sheet 2 of 2



5Y 2.5/1 blk.

UNIT 1 THROUGHOUT

Color | BiotIn