90-148A

ENTERED INTO DB

D Goodrow

...n SFB 021290/7A 90-148A	Depth	Date Processed	NO CORE AVAILABLE
SOUTH SF BAY	Core Length	Photo	X-RADIOGRAPH ANALYSIS 092605

...et 1 of 2

General Description

X-RADIOGRAPH MEASURES FROM TOP OF CORE. NOT TOP OF CORE LINER.
MEASURES ON FILM LABELLED IN RED.

	Color	Biotin
10cm TOP OF UNDISTURBED CORE		
BURROWS		
27cm EROSION SURFACE W/SHELLS ABOVE		
41-42cm EROSION SURFACE		
DENSE		
MUDDY		
53cm BASE OF COQUINA		
- LAMINATED -		
57-58cm EROSION SURFACE		
SMALL BURROWS		



90-148A

e ID SFB021290/7A 90-148A

of 2

Color Biotur

LAMINATED

LAMINATED

~~END OF CORE 140cm~~ 140cm EROSION SURFACE(?)

146.5cm END OF CORE ~~SPACER~~