90-149

ENTERED INTO KB D WOODROW

...n SFB 02129018 90-149	Depth	Date Processed	NO CORE AVAILABLE ?
SOUTH SF BAY	Core Length	Photo	X-RADIOGRAPH ANALYSIS 092605

...et 1 of 3

General Description

X-RADIOGRAPH MEASUREMENTS FROM TOP OF CORE.
[TOP OF CORE 0 - 43cm DISCOLORED BY CHEMICALS]
SPLIT-CORE LOG MEASURES TOP OF CORE LINER. IN 90-149 TOP OF CORE LINER = TOP OF CORE; NO GAP



3cm EROSION SURFACE (?)

SHELLS

GAP

29cm BASE OF SHELLY ZONE



Color	Biotin

90-149

e ID SFB021290/8 90-149

2 of 3

Color Biotin



WISPY, VERTICAL INTERTWINING FRACTURES. 100-150cm

90-149

Core ID SFB 0212908 90-149

Sheet 3 of 3

			Color	BiotIn
160		163-166cm EROSION SURFACE GAP		
170		174.5 END OF CORE		
180				
190				
200				
210				
220				
230				