90-174B

90-174B ENTERED INTO DB

Core ID SFB0220A/1B	Depth	Date Processed 040905
Section SOUTH SFBAY	Core Length	Photo X-RADIOGRAPH ANALYSIS 032805

Sheet 1 of 2

General Description



UNIT #1 CLAY, SILTY, TOUGH, 5Y 4/2, 0-58cm FEW SHELLS. HORIZ LAMINAE. BOTTOM SHARP.

UNIT #2 CLAY & SANDY CLAY, TOUGH 58-76 cm 5Y 3/2 & 5Y 4/2 AS IN #1 T/N SAND LENSES AS IN LOG. " DISSEMINATED IN CLAY TOWARDS BASE. FEW SHELLS. BASE SHARP, NO FIZZ.

90-174B

Core ID SFB022090/1B 90-174B

2 of 2

Color Biotin



FRACTURE

FRACTURE

80 | 5Y 3/2 DK OL GRY (UNOXIDIZED)

FS

SHELLS

UNIT #3 CLAYY, AS AT #1 BUT W/ HORIZ. LAMINAE 78-126 DISRUPTED AS IF BY BURROWS

90 |

SHELL

100 |

FRACTURE

UNIT #3

110 |

120 |

GAP W/ MUD IN IT. BURROWS

130 | 130.5cm BASE OF CORE.

140 |

150 |